

EM - 50
MILESTONE ACHIEVEM ENT

	FISCAL YEAR-TO-DATE				REMAINING SCHEDULED			
MILESTONE TYPE	Completed Early	Completed On Schedule	Completed Late	Overdue	Forecast Early	Forecast On Schedule	Forecast Late	TOTAL FY 2000
Enforceable								
Agreement	0	0	0	0	0	0	0	0
DOE-HQ	0	0	0	0	0	13	4	17
FO	0	0	0	0	0	0	0	0
RL	2	1	0	6	0	49	8	66
Total Project	2	1	0	6	0	62	12	83





EM-50 Exceptions

BASELINE FORECAST

Number Level Milestone Title Date Date

OVERDUE - 6

009DD61/3 RL Award Contract for Robotic Work 10/15/99 1/31/00

2.1.1 (AMT) Platform

Cause: RFP was sent out to all potential vendors. Review of submittals has delayed issuance of

the contract. **Impact:** None

Corrective Action: The contract will be awarded in January 2000.

49MW21/C-2 RL Produce Report Mapping the Matrix Space 11/15/99 Proposed in Hanford Waste Boxes Deletion

Cause: Activities at WRAP were focused on preparing shipments to WIPP.

Impact: None

Corrective Action: Funding for this TTP was returned to the Mixed Waste Focus Area. This

task is cancelled.

49MW21/B-4 RL Issue Software Test Reports 12/01/99 Proposed **2.1.1 (AMT)** in Hanford Waste Boxes Deletion

Cause: Activities at WRAP were focused on preparing shipments to WIPP.

Impact: None

Corrective Action: Funding for this TTP was returned to the Mixed Waste Focus Area. This

task is cancelled.

09WT22/C11 RL Issue Hanford Data Requirements for 12/15/99 03/31/00

2.1.1 (AMT) Operational Improvement Tests **Cause:** Projects are reviewing user needs for this activity.

Impact: None

Corrective Action: The Tanks Focus Area, ORP, and CH2M Hill are discussing redefinition of scope, assignment and funding for this task. As soon as this task is redefined, a change request and revised TTP will be submitted.

09WT22/C41 RL Issue Func. Requirements for Variable 12/15/99 03/31/00

2.1.1 (AMT) Depth Transfer Pump

Cause: Projects are reviewing user needs for this activity.

Impact: None

Corrective Action: The Tanks Focus Area, ORP, and CH2M Hill are discussing redefinition of scope, assignment and funding for this task. As soon as this task is redefined, a change request and revised TTP will be submitted.

Environmental Management Performance Report – December 1999 Section I – EM - 50

008WT51/1 RL Issue Product Delivery Expectations on 12/15/99 02/10/00

2.1.1 (AMT) Technologies for Remote Pit Enhancements

Cause: Impact: None

Corrective Action: The Memorandum of Understanding is in the process of being established. A River Protection Project Project Manager has been selected. This milestone will be complete in February, 2000.

FORECAST DELAY - 12

030C211/A01 HQ Complete Comprehensive Report on 9/30/00 12/31/00

3.5.6 (AMT) Instrument Development

Cause: This milestone has been delayed because prerequisite decision requirements for the separation process have not yet been made, and are not expected until the middle of January 2000.

Impact: None

Corrective Action: A revised TTP will be generated after replanning is completed.

030C211/A11 HQ Complete Demonstration of Gamma 8/31/00 9/30/00

3.5.6 (AMT) Spectrometer

Cause: This milestone has been delayed because prerequisite decision requirements for the separation process have not yet been made, and are not expected until the middle of January 2000.

Impact: None

Corrective Action: A revised TTP will be generated after replanning is completed.

030C211/A21 HQ Complete Demonstration of Neutron 4/30/00 9/30/00

3.5.6 (AMT) Counting System

Cause: This milestone has been delayed because prerequisite decision requirements for the separation process have not yet been made, and are not expected until the middle of January 2000.

Impact: None

Corrective Action: A revised TTP will be generated after replanning is completed.

09WT22/A11 RL Complete Functional Requirements for 3/10/00 6/30/00

2.1.1 (**AMT**) Sluicing of Tanks Beyond C-1

Cause: Projects are reviewing user needs for this activity

Impact: None

Corrective Action: The Tanks Focus Area, ORP, and CH2M Hill are discussing redefinition of scope, assignment and funding for this task. As soon as this task is redefined, a change request and revised TTP will be submitted.

Environmental Management Performance Report – December 1999 Section I – EM - 50

09WT22/C21 RL Complete Functional Requirements for 4/30/00 7/31/00

2.1.1 (**AMT**) Sluicing of Tanks Beyond C-1

Cause: Projects are reviewing user needs for this activity

Impact: None

Corrective Action: The Tanks Focus Area, ORP, and CH2M Hill are discussing redefinition of scope, assignment and funding for this task. As soon as this task is redefined, a change request and revised TTP will be submitted.

09WT22/C31 RL Complete Functional Requirements for 4/30/00 7/31/00

2.1.1 (AMT) Sluicing of Tanks Beyond C-1 **Cause:** Projects are reviewing user needs for this activity

Impact: None

Corrective Action: The Tanks Focus Area, ORP, and CH2M Hill are discussing redefinition of scope, assignment and funding for this task. As soon as this task is redefined, a change request and revised TTP will be submitted.

035C223/A11 HQ Project Review 2/11/00 3/31/00

3.5.6 (AMT) Issue Phase D Test Report

Cause: Project review date has been delayed by Subsurface Contaminants Focus Area to mid-

March.

Impact: None

Corrective Action: Change Request # PTD00-011 has been submitted to RL to revise the

milestone date.

036WT51/A14 RL Complete Test of 50-HP Flygt Mixer and 1/30/00 4/30/00

3.5.4 (AMT) Issue Phase D Test Report

Cause: During November, a preliminary test of the Flygt Mixer was conducted to check out the test system & the DAS. A propeller blade failed during a water operation on Nov 17, 1999 & will be replaced mid-January. Due to this delay, the mixer run-in test cannot be completed on schedule.

Impact: None

Corrective Action: A change request will be submitted to delay this milestone completion date.

037C131/A11 RL Participate in the AEAT Outline Design 3/31/00 06/30/00

3.5.6 (AMT) Review

Cause: PNNL staff activities are currently on hold until activities are kicked off for the parent program, the Nested, Fixed-Depth Fluidic Sampler and At-Tank Analysis System Program, RL08WT22.

Impact: None

Corrective Action: Milestone will be revised upon resolution of RL08WT22.

037C131/A12 RL Issue Letter Report on Nested Sampler 7/15/00 10/15/00

3.5.6 (AMT) Cold Test Recommendations

Cause: PNNL staff activities are currently on hold until activities are kicked off for the parent program, the Nested, Fixed-Depth Fluidic Sampler and At-Tank Analysis System Program, RL08WT22.

Impact: None

Corrective Action: Milestone will be revised upon resolution of RL08WT22.

Environmental Management Performance Report – December 1999 Section I – EM - 50

037C131/B11 RL Issue Design Recommendations and 2/15/00 7/15/00

3.5.6 (AMT) Specifications for Enhanced Pit Operations

Cause: PNNL staff are under a hold for technical activities pending authorization of support

funding on the W-314 Project/Tank Farm Operations side.

Impact: None

Corrective Action: Milestone will be revised upon resolution of W-314.

037WT31/B32 RL Issue Next "Phase" Test Matrix for 1/30/00 3/30/00

3.5.4 (AMT) INEEL CVS Study

Cause: Task will begin once projected waste compositions are available from INEEL. This input was scheduled by the end of November and hasn't yet been delivered. The status was discussed in a meeting with the end-users, the TFA TIM and co-investigators. The current scheduled completion date of 3/30/00.

Impact: None

Corrective Action: This milestone will be completed by March 30, 2000. Task will begin once projected waste compositions are available form INEEL.

OVERDUE - 3 (FY 1999)

08WT21/C1 HQ Document Deployment of the Corrosion 9/30/99 1/10/00

2.1.1 (**AMT**) Probe

Cause: Tank Farm Operations priorities and work package review issues have delayed this task

until January 2000. **Impact:** None

Corrective Action: The probe will be deployed January 13, 2000.

08WT22/H-1 RL Issue Revised Deployment Strategy 8/30/99 2/28/00

2.1.1 (AMT) and Plan

Cause: The strategy of this task has been modified to include a mobile sampler system, which

has caused the revision of this plan to be delayed.

Impact: None

Corrective Action: This plan will be issued by 2/28/00.

49MW21/A-2 RL Submit BWAS Characterization Plan 8/31/99 Proposed

2.1.1 (AMT) Deletion

Cause: Activities at WRAP were focused on preparing shipments to WIPP.

Impact: None

Corrective Action: Funding for this TTP was returned to the Mixed Waste Focus Area. This

task is cancelled.